

Calibration Of 1ph Energy Meter



This set up will consist of following facilities:-

- + Transparent type 1 Phase Energy Meter.
- + Digital A.C. Ammeter / A.C. Voltmeter.
- + In built loading unit.
- + Appropriate wattmeter.
- + Stop Watch.
- + Built in control circuit and protection circuit

Measurement Of Power By 3 Voltmeter And 3 Ammeter Method

This set up will consists of following facilities:-

- + Digital Voltmeter 3 Nos.
- + Digital Ammeter 3 Nos.
- + Choke Coil (Stepless Variable)
- + 1 Phase Auto Transformer and Suitable Rheostats.
- + Built in control circuit and protection circuit duly wired.



Measurement Of Power In A 3 Phase System By Two Wattmeter Method

This set up will consists of following facilities:-

- + Digital A.C. Ammeter/ A.C. Voltmeter.
- + Appropriate Wattmeter 2 Nos.
- + In built loading unit.
- + Built in control circuit and protection circuit duly wired.